
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/9/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ☑ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S02CC1007MH	Test ID: <u>D1032-027009</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S02CC1007MH
0			Water Level	
23.70000076			Dye Test Visible	DYE SEEN AT JOINT
40.5			Abandoned Survey	DYE TSET IS COMPLETE